

POSTED  
at 13.h40

Stewards  
Log N° 43..

---

From The Technical Delegate  
To The Stewards of the Meeting

---

Report N° 04

After the qualifying session we have checked cars 7, 8, 34, 50, 53 and 111 on:


1. Weight
2. Ride Height
3. Wing position
4. Restrictor sealing
5. Engine settings
6. Gearbox ratios
7. Boost on Turbo cars

After the final checks all cars are complying with their current homologation files and the bop decisions.

Tyres on the cars were all from the entered tyre sheets

There's nothing to report.

After request from the Stewards we've checked cars 44 and 78 on engine sealing and engine setting. All was ok.

  
SRO S. BUREAU  
C. SURMONT.

**Claude Surmont**

Technical Director SRO

Technical Delegate for this event

Lic RACB n°2774

  
TO BE PUBLISHED  
M. Janssen  
Chairman

Date 25 June 2016

Time 13:00

Document

Copy to: The Race Director

The Clerk of the Course

The Secretary of the Meeting

POSTED  
at 13.h40

Stewards  
Log N° 43..

---

From The Technical Delegate  
To The Stewards of the Meeting

---

Report N° 04

After the qualifying session we have checked cars 7, 8, 34, 50, 53 and 111 on:

1. Weight
2. Ride Height
3. Wing position
4. Restrictor sealing
5. Engine settings
6. Gearbox ratios
7. Boost on Turbo cars

After the final checks all cars are complying with their current homologation files and the bop decisions.

Tyres on the cars were all from the entered tyre sheets

There's nothing to report.

After request from the Stewards we've checked cars 44 and 78 on engine sealing and engine setting. All was ok.

  
SRO S. BUREAU  
C. SURMONT.

**Claude Surmont**

Technical Director SRO

Technical Delegate for this event

Lic RACB n°2774

  
TO BE PUBLISHED  
M. Janssen  
Chairman

Date 25 June 2016

Time 13:00

Document

Copy to: The Race Director

The Clerk of the Course

The Secretary of the Meeting