

POSTED
at 15h35

From The Technical Delegate Report N° 03
To The Stewards of the Meeting and to whom it may concern

Having inspected car 7 after its accident the conclusions are :

- Car 7 can't be repaired here as front chassis elements damage needs welding and replacement
- The findings have been written in the Technical Passport of the car

Alain Marquet (RACB Lic 2265)
Series Technical Delegate



Date 17 September 2016

Time 15:00

Document

Copy to: The Race Director
The Clerk of the Course
The Secretary of the Meeting

TO BE PUBLISHED

M. Janssen
Chairman

