

Date: 06th May 2017

Event: Brands Hatch Sprint series

Team: Reiter Engineering

Number: 24

Status: Stop after FP 2

Reason: Car crashed in FP 2; chassis defect - not able go on

Name: Dennis Schäfer

Signature: 