

POSTED
at 09h10m

Stewards
Log N° 32



From The Technical Delegate
To The Stewards of the Meeting

Report N° 02 bis

All drivers' equipment have been checked and are ok.

All refuelling towers have been checked on measurements, position and refuelling rig restrictors, all is ok.

Claude Surmont

Technical Director SRO
Technical Delegate for this event
Lic RACB n°2774

Date 25 June 2016

Time 08:00

Document

Copy to: The Race Director

The Clerk of the Course

The Secretary of the Meeting

TO BE PUBLISHED

M. Jansen
Chairman